



LEXMARK W820


XEROX N4525/N24/N32/N40

IBM 1145/4332

Turn the printer off, unplug it, and allow it to sit for 30 minutes before performing these maintenance steps

FUSER INSTALLATION:

1. LINE UP CONNECTOR ON FUSER WITH CONNECTOR ON PRINTER
2. HOLD ON TO THE FUSER HANDLES AND SLIDE THE FUSER INTO THE PRINTER
3. FIRMLY PUSH THE FUSER TO MAKE SURE IT IS SECURELY CONNECTED
4. TIGHTEN THE TWO THUMBSCREWS



REMOVE SHIPPING SCREWS BEFORE INSTALLATION